

Caprolactam Extract

## VISUAL TANK INSPECTION REPORT

Vessel :
Port/Terminal:

Product/Cargo:

ETT-114

Hercules Shipyard / Freeport, Texas

Your Reference:

Our Reference: FP/97-5145

Date

: March 7, 1997

Tank				
Number	1C	2C	3C	
Tank			• • • • • • • • • • • • • • • • • • • •	
Coating	Mild Steel	Mild Steel	Mild Steel	
Last				
Cargo	99.9% Cyclohexane 99.9% Cyclohexane 99.9% Cyclohexane			
Second Last				
Cargo				
Third Last				
Cargo				
Jisual Cleanliness				
Accepted *	Accepted	Accepted	Accepted	
/isual Cleanliness	<del></del>			
Rejected *				
Cime/Date	1825	1825	1825	
Inspected	03/07/97	03/07/97	03/07/97	

Method said to have been used to clean tanks: Tanks #1 Center, #2 Center, #3 Center and Lines: Stripped and Blown.

Information regarding previous cargoes, tank coating and cleaning method was obtained from vessel personnel and cannot be guaranteed as accurate by Caleb Brett U.S.A., Inc. and no liability can be assumed for errors resulting from improper information supplied. This report, of necessity, is based on such information.

\* The cleanliness of inspected tank(s) is/are based on visual inspection of tank surfaces and line system at accessible areas only. This document does not cover the cleanliness of tank surfaces and line system at inaccessible spots and/or possible release of components of previous cargoes during loading, discharge or transport of the cargo in question, for which the vessel is fully responsible. Suitability of tank coating for intended cargo must be guaranteed by vessel's owner or by suppliers of the coating.

I T S-Caleb Brett